Report Documentation Page			Form Approved OMB No. 0704-0188		
Public reporting burden for the collection of information is estimated to maintaining the data needed, and completing and reviewing the collect including suggestions for reducing this burden, to Washington Headqu VA 22202-4302. Respondents should be aware that notwithstanding ar does not display a currently valid OMB control number.	tion of information. Send comments narters Services, Directorate for Information	regarding this burden estimate of mation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington	
1 DEDORT DATE	2 DEPORT TYPE		2 DATES COME	The h	
1. REPORT DATE 20 APR 2007	2. REPORT TYPE Technical, Success	Story	3. DATES COVE 09-11-2006	6 to 20-04-2007	
4. TITLE AND SUBTITLE			5a. CONTRACT NUMBER		
T55 Compressor Rotor Turn Time Reduction - Phase I			5b. GRANT NUMBER		
			5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)			5d. PROJECT NUMBER 06-0107-08		
			5e. TASK NUMBER		
			5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) National Center for Defense Manufacturing & Machining,1600 Technology Way,Latrobe,PA,15650		1600	8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)		
			11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution	ion unlimited				
13. SUPPLEMENTARY NOTES					
The T55 jet engine used in the CH-47 (Figure #2) compressor rotor. After so manufacturers (OEM) specifications. On numerous set-ups resulting in a turn at rotor. Due to a change in compressor meed of a grinding center to reduce the which is not present on the T712 (Figur Machining (NCDMM) was requested to the process. This solution is to elim 4 to 5 assemblies be ground per day.	long, these compress Corpus Christi Arm round time of 15 to rotors from the T712 e cycle time and to ac are #1). The National to evaluate the curre inate the multiple so	ssor rotors need r y Depot's (CCAI 16 hours to comp 2 (Figure #1) to th ccommodate the a l Center for Defen ent process and particular	rebuilt to origo current proletely refurbate T714 (Figuaddition of a nse Manufactoride a total ethe current	ginal equipment ocess requires ish the compressor are #2), CCAD is in 17.5" shroud turing and I grinding solution cycle time to allow	
National Center for Defense Manufact helicopter; Success Stories	turing and Machinin	g; NCDMM; T5	5 jet engine;	CH-47 Chinook	
16. SECURITY CLASSIFICATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON	

1

c. THIS PAGE

unclassified

b. ABSTRACT

unclassified

a. REPORT

unclassified

1



T55 Compressor Rotor Turn Time Reduction – Phase I



NCDMM Project No. 06-0107-08

PROBLEM / OBJECTIVE

The T55 jet engine used in the CH-47 Chinook helicopter contains either the T712 (Figure #1) or the T714 (Figure #2) compressor rotor. After so long, these compressor rotors need rebuilt to original equipment manufacturers (OEM) specifications. Corpus Christi Army Depot's (CCAD) current process requires numerous set-ups resulting in a turn around time of 15 to 16 hours to completely refurbish the compressor rotor. Due to a change in compressor rotors from the T712 (Figure #1) to the T714 (Figure #2), CCAD is in need of a grinding center to reduce the cycle time and to accommodate the addition of a 17.5" shroud which is not present on the T712 (Figure #1).

The National Center for Defense Manufacturing and Machining (NCDMM) was requested to evaluate the current process and provide a total grinding solution for the process. This solution is to eliminate the multiple set-ups and reduce the current cycle time to allow 4 to 5 assemblies be ground per day.

ACCOMPLISHMENTS / PAYOFF



Figure #1 T712 Compressor Rotor Assembly



Figure #2 T714 Compressor Rotor Assembly

Process Improvement

Due to the uniqueness of the operation along with the size of the compressor rotor assembly, very few state-of-the-art machine choices exist. Danobat Machine Tool Company manufactures a complete line of machines specifically for blade tip grinding. The Dantip R1 400/600 CNC High Speed Grinding, Deburring and Measuring Machine (Figure #3) is one option chosen for this operation. The second option is a Hardinge supplied Kellenberger Kel-Varia grinding machine/Marposs gauging system combination (Figure #4). Both options offer quality and reliability in the field of grinding.



Figure #3 Danobat



Figure #4 Kellenberger

Implementation and Technology Transfer

The Danobat solution requires only one set-up resulting in a cycle time of approximately 3 hours per assembly. The Kellenberger/Marposs combination requires at least two set-ups due to the off-line gauging system resulting in a cycle time of 7 to 8 hours per assembly.

By implementing one of the above solutions, CCAD will have the ability to increase their production of the T712 and T714 compressor rotors to meet the needs of today's warfighters.

Expected Benefits

Expected Cost/Time Savings:

The Danobat solution, with a cost of nearly \$1.2M, generates annual savings of \$162,500 machining 100 units/year. This results in a 7.3-year payback.

The Kellenberger/Marposs solution, with a cost of nearly \$850K, generates annual savings of \$112,500 machining 100 units/year. This results in a 7.5-year payback.

TIME LINE / MILESTONE

Start Date	November 06
End Date	April 07

PROJECT FUNDING

NCDMM Funding.....\$40K

PARTICIPANTS

Danobat Machine Tool Company Hardinge Inc. NCDMM

THE INFORMATION IN THIS TECHNICAL REPORT REFLECTS THE U.S. ARMY'S DEPLOYMENT OF CERTAIN TECHNOLOGIES AND IS NOT AN ENDORSEMENT OF ANY COMPANIES, SERVICES, OR PRODUCTS.

For additional information about the NCDMM, please visit our website at www.ncdmm.org